
FIG. 1



2/4

FIG. 2A




FIG. 2B




FIG. 2C





FIG. 2D








FIG. 3B




FIG. 3C





FIG. 3D



REFERENCE NUMERALS IN THE DRAWINGS

1 1 Substrate

hus.

- 2 1 Photomask Ag-paste film
- 21a, 21b Region
- 2 2 First photomask
- 22a, 24a Exposure part
- 22b Dust
- 24, 24b Second photomask